



HD Visual Communication Unit
KX-VC1300/KX-VC1600
(Software Ver4.15)

Release Note

Ver1.00

27th Feb. 2015

Panasonic System Networks Co., Ltd.

Table of Contents

1. INTRODUCTION.....3

1.1.PURPOSE3

1.2.OBJECT MODEL3

1.3.DISCLOSURE SCOPE3

1.4.CONTENTS3

2. UPDATE INFORMATION FOR KX-VC1300/VC16004

3. TRADEMARKS AND LICENSES.....5

3.1.TRADEMARKS5

3.2.LICENSES5

1. Introduction

1.1. Purpose

This release note mentions about software version 4.15 for HD visual communication unit KX-VC1300/1600.

1.2. Object Model

Object models for this release note are as follows.

Model	Note
KX-VC1300	
KX-VC1600	

※Ver4.15 does not support KX-VC500, KX-VC300 and KX-VC600.

1.3. Disclosure scope

Disclosure scope is for the end-user, sales companies, Sler and dealers which are in charge of system up, setting and maintenance.

1.4. Contents

This release note mentioned as follows.

- Update information for Ver4.15

2. Update information for KX-VC1300/VC1600

Regarding software Ver.4.15, the following list shows the new function and update information comparing to software Ver. 4.10.

Yes : Supported, No : Unsupported(unavailable)

Item	Function	Remarks	Object Model	
			VC1600	VC1300
Improvement of Functions	GUI language	<ul style="list-style-type: none"> German, French, Italian and Dutch are supported as GUI language. (only Global model) Ver4.20 will support for JP model and CH model. 	Yes	Yes
	Routing Settings expansion for LAN2	<ul style="list-style-type: none"> The number of the routing settings of LAN2 is extended from 10 to 50. 	Yes	No
	Receiving sensitivity improvement of the remote control	<ul style="list-style-type: none"> The receiving sensitivity is improved by changing receiving treatment of the remote control. 	Yes	Yes
	HDMI Equipment connectivity improvement	<ul style="list-style-type: none"> The connectability of the HDMI equipment is improved by changing the detection process, when a HDMI device generates non-standard signal. 	Yes	Yes
	Screen at the start/stop of content sharing	<ul style="list-style-type: none"> The phenomenon that screen might flicker at the start or the end of displaying computer's screen and the sub video camera's image is fixed. 	Yes	Yes
	Connectability improvement with VC300/600	<ul style="list-style-type: none"> Connectability is enhanced in case connecting with KX-VC300/VC600 which are installed under NAT router and they are set up Static NAT. 	Yes	Yes
	System Initialization	<ul style="list-style-type: none"> The internal process for initializing the system is changed. 	Yes	Yes

3. Trademarks and Licenses

3.1. Trademarks

Polycom® is a trademark owned by Polycom, Inc. in the US and other countries.

3.2. Licenses

This product incorporates G.722.1 and G.722.1 Annex C licensed by Polycom®.