



◆ Blank Page Removal



<Function>

When scanning a set of documents that contains both single-sided and double-sided sheets, this function automatically skips over the blank sides. It saves you time and trouble by eliminating the need to sort the sheets beforehand or remove the blank data after scanning. It also helps reduce wasted memory space in your computer.



<ICP Setting Procedures>



1. Click "Scan"  at the left side. The "New Document – Scan" dialog box is displayed.
2. Click "Scan Setting" .
3. Select "ADF Duplex" under the Paper Source scroll box
4. Change the Image Type scroll box to "24bit Color"
5. Select the "Layout" tab
6. Check the "Blank Page Removal" box and "Show Result"
1. Click "OK"
2. Click the "Start" button to begin scanning.
9. "BlankPageSkip.txt" (Removed Page List) is displayed.

<Notes>

- The "Pixel Ratio" can be set by moving the slider or by directly inputting the value into the edit box.
- Some documents containing minimal information may be mistaken as blank pages, in which case they will be treated as a blank page and removed. In such case please adjust Pixel Ratio (%) accordingly.
- When scanning important documents, therefore, check after scanning that all the pages that should

have been scanned have in fact been scanned.

- This function cannot be used with flatbed scanning.
- When pre-scanning has completed, you can confirm the image's "Pixel Ratio (%)", which is displayed in the lower portion of the preview window.